(SRI M. V. KRISHNAPPA)

(c) Full remission of land revenue has been ordered in 13 villages and full suspension in 35 villages of this Taluk.

Takavi loans and loans for irrigation wells are being granted in order to give some relief to the agriculturists

Three relief works have also been started in order to provide employment to the people of this area.

ಶ್ರೀ ವೀರಭದ್ರಪ್ಪ ಈರಪ್ಪ.—ಈ ತಾಲ್ಲೂಕಿನಲ್ಲಿ ಮುಂಗಾರು ಬೆಳೆಗಳಾದ ಹತ್ತಿ, ಗೋಧಿ, ನೆಲಗಡಲೆ, ಮತ್ತು ಮುಸುಕಿನ ಜೋಳ ಮುಂತಾದ ರಬ್ಬಿ—ಇವುಗಳಿಗೆ ನಷ್ಟವಾಗಿರುವುದರಿಂದ ಅವುಗಳನ್ನು ಬೆಳೆಯುವ ರೈತರಿಗೆ ಕಂದಾಯ ಮಾಫಿ ಮಾಡುತ್ತೀರಾ ?

†ಶ್ರೀ ಎಂ. ವಿ. ಕೃಷ್ಣಪ್ಪ.—ಈಗ 13 ಹಳ್ಳಿಗಳಲ್ಲಿ ಪೂರ್ತಿಯಾಗಿ ಕಂದಾಯವನ್ನು ಮನ್ನಾ ಮಾಡಲಾಗಿದೆ. ಇನ್ನು 35 ಹಳ್ಳಿಗಳಲ್ಲಿ ಅರ್ಧ ಸಸ್ಪೆನ್‌ಷನ್ ಮಾಡಿದೆ. ಮುಂದೆ ಕ್ರಾಪ್ ಕಟಿಂಗ್ ಮಾಡುವಾಗ್ಗೆ ರಬ್ಬಿ ಬೆಳೆ ಏನಾದರೂ ಫೇರ್ ಆಗಿದೆಯೇ ಎಂಬುದನ್ನು ಇನ್‌ಸ್ಪೆಕ್ಷನ್‌ಮಾಡಿ, ವರದಿ ಕೊಡಬೇಕೆಂಬುದನ್ನು ತಿಳಿಸಿದ್ದೇವೆ. ಅಲ್ಲಿಂದ ವರದಿ ಬಂದ ತಕ್ಷಣ ತಕ್ಕ ಕ್ರಮವನ್ನು ತೆಗೆದು ಕೊಳ್ಳುತ್ತೇವೆ.

ಶ್ರೀ ವೀರಭದ್ರಪ್ಪ ಈರಪ್ಪ.—ಈ ತಾಲ್ಲೂಕಿನಲ್ಲಿ ಕೆಲವು ಕಡೆಗಳಲ್ಲಿ ಹಿಂಗಾರು ಬೆಳೆಗಳಿಗೂ ನಷ್ಟವಾಗಿದೆ ಎಂಬುದು ಸರ್ಕಾರದ ಗಮನಕ್ಕೆ ಬಂದಿದೆಯೇ ?

ಶ್ರೀ ಎಂ. ವಿ. ಕೃಷ್ಣಪ್ಪ.—ಅನೇಕ ಕಡೆಗಳಿಂದ ಆ ಬಗ್ಗೆ ವರದಿಯೇನೋ ಬರುತ್ತಾ ಇದೆ. ಕೆಲವು ಕಡೆಗಳಲ್ಲಿ ಆ ಬೆಳೆಗಳೂ ಕೂಡ ನಷ್ಟವಾಗಿವೆ ಎಂಬುದಾಗಿ ಮಾನ್ಯ ಸದಸ್ಯರೂ ಕೂಡ ಆಗಾಗ್ಗೆ ನನಗೆ ಕಾಗದ ಬರೆಯುತ್ತಿದ್ದಾರೆ.

Progress of work in the Kabini Project.

* *Q.*—392. Sri D. M. SIDDAIAH (Biligere).—

Will the Government be pleased to state :—

(*a*) the progress of work so far done in the Kabini Project of H.D. Kote Taluk, Mysore District;

(*b*) the amount estimated and the amount spent so far;

(*c*) the number of acres of land that come under cultivation and the irrigable area that would be covered;

(*d*) the area coming under submersion and how much is forest land and how much is revenue land;

(*e*) whether the submersible land is released to go ahead with the work;

(*f*) when the project is expected to be completed ?

A.—Sri S. NIJALINGAPPA (Chief Minister).—

(*a*) The work on the Kabini Dam and earthen flanks is in progress. In the spill-way portion, masonry has been raised up to ten feet above the river bed level for a length of 120 feet. In the remaining length, the masonry work is in progress at different levels.

(*b*) The sanctioned esti nated amount of Rs 320·00 lakhs. The is amount spent up to end of February 1964 is 125·15 lakhs.

(*c*) 30,000 acres.

(*d*) 11,740 acres comprising of State Forest—585 acres District Forest and Government Waste lands—815 acres; Revenue lands—6,780 acres; River, tank-bed, roads and valleys—3,560 acres.

(*e*) Acquisition of submersible lands under private holding and release of forest lands is in progress.

(*f*) During the fourth Five-Year Plan period.

Sri D. M. SIDDAIAH.—Supplementary to (*b*): May I know the revised estimated amount and also the number of acres to be brought under irrigation?

† **Sri S. NIJALINGAPPA.**—The revised estimate is Rs. 10 crores and the area that comes under irrigation is 45,000 acres.

Sri D. M. SIDDAIAH.—Supplementary to (*a*): May I know the present height of the dam? Is it not a fact that technical opinion is to increase the height to 14 feet to irrigate more area?

Sri S. NIJALINGAPPA.—At the second stage it ought to be 12 to 14 feet in height.

ಶ್ರೀ ಎನ್. ರಾಚಯ್ಯ.—ತುಂಗಭದ್ರಾ ಮತ್ತು ಶರಾವತಿ ಜಲಾಶಯಗಳ ಕೆಳಭಾಗದಲ್ಲಿರ ತಕ್ಕ ರೈತರಿಗೆ ಒದಗಿಸುತ್ತಿರುವ ಅನುಕೂಲಗಳನ್ನು ಕಪಿನಿ ಮತ್ತು ನುಗು ಜಲಾಶಯಗಳ ಕೆಳಭಾಗದಲ್ಲಿರತಕ್ಕ ರೈತರಿಗೂ ಒದಗಿಸುತ್ತೀರಾ?

ಶ್ರೀ ಎಸ್. ನಿಜಲಿಂಗಪ್ಪ.—ಹೌದು. ಆ ರೀತಿಯಾಗಿಯೇ ಅನುಕೂಲಗಳನ್ನು ಒದಗಿಸುತ್ತಾ ಇದ್ದೇವೆ.

ಶ್ರೀ ಎನ್. ರಾಚಯ್ಯ.—ಇದುವರೆಗೆ ನುಗು ಜಲಾಶಯದ ಕೆಳಭಾಗದಲ್ಲಿರತಕ್ಕ ರೈತರಿಗೆ ಯಾವ ಅನುಕೂಲಗಳನ್ನೂ ಒದಗಿಸದೆ ಅಲ್ಲಿನ ರೈತರ ಜಮೀನುಗಳನ್ನು ಅಕ್ವೈರು ಮಾಡಿಕೊಂಡರೂ ಇನ್ನೂ ಅನೇಕರಿಗೆ ಕಾಂಪೆನ್‌ಸೇಷನ್ ಕೊಡದೇ ಇರಲು ಕಾರಣವೇನು?

ಶ್ರೀ ಎಸ್. ನಿಜಲಿಂಗಪ್ಪ.—ನುಗು ಜಲಾಶಯದ ವಿಚಾರ ಬಂದಾಗ್ಗೆ ಅದಕ್ಕೆ ಉತ್ತರ ಹೇಳ ತ್ತೇನೆ. ಈ ಪ್ರಶ್ನೆ ಕಪಿನಿ ಜಲಾಶಯಕ್ಕೆ ಸಂಬಂಧಪಟ್ಟದ್ದು.

Supply of Power to I. P. sets in Pavagada taluk.

Q.*—437. **Sri R. KENCHAPPA (Pavagada).—

Will the Government be pleased to state:—

(*a*) the number of cases in which the Power has not been supplied to I. P. sets for irrigation purposes in Pavagada taluk in spite of the ryots having deposited the amount;

(*b*) whether is has come to their notice that scarcity of wire is the cause for this delay;

(*c*) the length of wire required for servicing pump-sets in this taluk;

(*d*) whether they will take suitable steps to supply necessary materials specially wire for servicing I. P. sets in this taluk, in view of this taluk being a scarcity area?